

Works Identified by Ken Hussey January 2021.

To be done “In-House”

| Issues | Recommendation (s) | Cost | When by |
|----------------------------------|--|------|-------------|
| Goal Posts | Secure Nets and Instruct BTC to remove pegs before mowing and replace after. | TBA | ASAP |
| Play Area Fence | Replace broken slates | TBA | DONE |
| Play Area Fencing / Gate | Treat with suitable timber preservative | TBA | April |
| Wooden play equipment components | Treat with suitable timber preservative | TBA | April |
| Overhead power signs | Fix in suitable locations (signs to be provided by Ken Hussey) | | April |
| Water hazard signs | Fix in suitable locations (signs to be provided by Ken Hussey) | | April |

Could be done “In House”.

| Issues | Recommendation (s) | Cost | When by |
|---------------------------------------|---------------------------|------|---------|
| Access to water hazard from Play Area | Replace / improve fencing | TBA | April |

Costs for other works if supplied / carried out by Ken Hussey

| Issues | Recommendation (s) | Supply Only | Supply & fit | When by |
|---|--|-------------|--------------|------------------|
| Bridge with Hut - supports need replacement | Supply & fit two new crossbars and fittings | | £297.00 | April |
| Overhead power signs | Provide overhead power signs | | £7.50 each | ASAP |
| Water Hazard signs | Provide water hazard signs | | £7.50 each? | ASAP |
| Access to water hazard from Play Area (See Note 1) | Fence needs replacing, bench needs moving | | POA | ASAP. |
| Seesaw - Possible compaction issues (See Note 2) | Grass mats recommended (min 6) | £180 | £255.00 | |
| Burma Bridge - Original timbers decaying | Supply and fit new timbers to Burmese bridge | | £415.00 | Within 18 months |

Note 1. Does the bench really need to be moved if the fencing is sufficiently high? Needs to be investigated. The bench has been there for many years without incident.

Note 2. This is only a recommendation.